

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	nAPP2119332043
District RP	
Facility ID	
Application ID	

## Release Notification

### Responsible Party

Responsible Party	OWL SWD Operating, LLC	OGRID	308339
Contact Name	Mr. Phillip Sanders	Contact Telephone	210-906-3551
Contact email	psanders@oilfieldwaterlogistics.com	Incident #	(assigned by OCD)
Contact mailing address	8201 Preston Road, Suite 520, Dallas, Texas 75225		

### Location of Release Source

Latitude 32.067333 Longitude -103.648139  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Harrier Line Conoco Phillips	Site Type	Oil Producing Pad
Date Release Discovered	6/29/2021	API#	(if applicable)

Unit Letter	Section	Township	Range	County
N	02	26S	32E	Lea

Surface Owner: ☒ State ☐ Federal ☐ Tribal ☐ Private (Name: SLO)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 5 BBLs	Volume Recovered (bbls) 5 BBLs
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: Release occurred when OWL was removing a section of the discontinued Harrier Poly Line, causing 5 barrels of produced water to be spilled.

Incident ID	nAPP2119332043
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? If YES, for what reason(s) does the responsible party consider this a major release?

release as defined by 19.15.29.7(A) NMAC?

☐ Yes ☒ No

If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Notification of the release was given by Travis Reddick of KJE to Robert Hamlet, OCD and Ryan Mann, SLO via email.

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

- ☒ The source of the release has been stopped.
- ☒ The impacted area has been secured to protect human health and the environment.
- ☒ Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.
- ☒ All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

N/A

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Phillip Sanders

Title: HSE Director

Signature: [Signature]

Date: 7/9/21

email: \_\_\_\_\_

Telephone: 432-269-3735

#### OCD Only

Received by: Ramona Marcus

Date: 7/14/2021