District 1 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			Rele	ease Notific	ation	and Co	orrective A	ction			
						OPERA	FOR	(🛛 Initia	al Report [Final Repo
Name of Company Torch Energy Services, Inc.					Contact Melanie Reyes						
Address 2600 W. I-20, Odessa, TX 79763					Telephone No. (432) 580-8500						
Facility Na	me	Cooper Jal U	Init- Test	Satellite #2		Facility Typ	e Oil Pro	oductio	n Test Sit	e	
Surface Ow	ner	RRR Ranc	h	Mineral C)wner	Cooper	Jal Unit		Lease N		2966
				LOCA	TION	N OF REI	LEASE A	P1#	30.02	5.09637.0	00.00
Unit Letter Section H 24		Township 24SRange 36EFeet from t 1695		Feet from the 1695		South Line orth	Feet from the 990		Vest Line ast	County Lea	
			La	titude_ <u>32.2054</u>	03	_ Longitud	le_103.213538				
				NAT	URE	OF REL	EASE				
Type of Release Salt Water with 5% Oil Cut						Volume of Release 230 Barrels Volume Recovered 230 Barrels					
Source of Release Tank Overflow						Date and Hour of OccurrenceDate and Hour of Discovery9/9/08 5:00 AM9/9/08 7:00 AM					
Was Immediate Notice Given?						If YES, To Whom? To the NMOCD in Hobbs, NM					
By Whom? Randy McAnally						Date and Hour 9/9/08 10:00 AM					
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse. NA					
If a Waterco	urse was Im	pacted, Descr	ibe Eully 4	······		L					
il a waiçico	uise was till	ipacieu, Desci	loc Fully.								
NA			· `								
Describe Ca	use of Probl	em and Reme	dial Action	n Taken.*							
The salt wate	er overflowe	ed the Test Sat	tellite Tan	k and ran down a	lease roa	ad. No pastu	re was affected.				
				5	π <i>e</i> τ	D BE D	ELINEATED	סד נ	'CLER	th' + ON	5
Describe Are	a Affected	and Cleanup /	Action Tak		· · · · · · · · · · · · · · · · · · ·						
The salt wate	er was picke	ed up by a vac	uum truck	from the lease ro	ad.						
regulations a public health should their or the enviro	Il operators or the envi operations h nment. In a	are required to ronment. The nave failed to a	o report ar acceptanc adequately)CD accep	d/or file certain r c of a C-141 repo investigate and r	clease no ort by the emediate	otifications as NMOCD m e contaminati	knowledge and u nd perform correc arked as "Final Re on that pose a thre e the operator of r	tive acti eport" d eat to gr	ions for rele loes not reli ound water	eases which may ieve the operato r, surface water,	y endanger r of liability human health
	10	11 1	0				OIL CON	SERV	ATION	DIVISION	
		11 14			Signature: MUL						
Signature:	11	LZ	1-				•	- Ser	-101	- soor	
Signature: Printed Nam	<u> </u>	Melanic Rey	es			Approved by	District Supporting	TONN	<u>AENTAL</u>	ENGINEE	R
******		Melanie Reyo					District Supervise			ENGINEE	
Printed Nam	E		tant				e: 9.22.08				.ටළ
Printed Nam Title: E-mail Addr Date:	E css: rey 9/17/0	ngineer Assist yesm@odessa	tant .teai.com Ph	one: (432) 580-8		Approval Dat Conditions of	e: 9.22.08	3 1	Expiration	Date: 11.21	.08