

OIL CONSERVATION DIVISION
RECEIVED

'93 JU 26 09 10 12

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2133-2916 Field: Bravo Dome

Location: 1811' FEL X 2085' NW T21N. R33E, SEC 27, UNIT G

DEPTH	ANGLE INCLINATION DEGREES
<u>498</u>	<u>1°</u>
<u>688</u>	<u>1 1/2°</u>
<u>1184</u>	<u>1 1/2°</u>
<u>1658</u>	<u>3/4°</u>
<u>2130</u>	<u>1°</u>
<u>2585</u>	<u>3/4°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Robert E. Perry

C. H. Redman
Title: SR