

OIL CONSERVATION DIVISION
REGISTERED

'93 JUL 10 AM 8 53

INCLINATION REPORT

Operator: Amoco Production Company Address: P. O. Box 606, Clayton, New Mexico 88415

Lease Name: Bravo Dome Carbon Dioxide Gas Unit Well No. 2134-191F Field: Bravo Dome

Location: 2001' FWL X 1874' FNL T21N, R34E, SEC 19, UNIT F

DEPTH	ANGLE INCLINATION DEGREES
<u>461'</u>	<u>1/4°</u>
<u>720'</u>	<u>1/2°</u>
<u>1203'</u>	<u>3/4°</u>
<u>1678'</u>	<u>1°</u>
<u>2162'</u>	<u>1°</u>
<u>2566'</u>	<u>1 1/4°</u>

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Robert R. Cunniff

Kath Stelmach
Title: Asst. Toolpusher