

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Drilling Well - P&A		5. LEASE DESIGNATION AND SERIAL NO. M00-C-1420-0982
2. NAME OF OPERATOR Shell Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Isleta Pueblo
3. ADDRESS OF OPERATOR 1700 Broadway, Denver, Colorado 80202		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 810' FNL and 640' FWL Section 7		8. FARM OR LEASE NAME Isleta Central
14. PERMIT NO.		9. WELL NO. #1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5066 KB, 5044 GL		10. FIELD AND POOL, OR WILDCAT Cactus Area
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NW/4 NW/4 Section 7-T7N-R2E
		12. COUNTY OR PARISH Valencia
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) <u>Cut casing, Perf</u> ☒	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Cut 7" csg @ 5244. Pulled 122 jts.
Cmt'd across stub w/reg cmt - .4% retarder (71' inside stub and 159 above) (7" cut inside 9-5/8" set @ 5334) 7/13/75. Perf'd Santa Fe SS 2600-2650 (USGS test). Covered w/50 sx plug 7/14/75. Perf'd Santa Fe SS 1390-1310 (USGS test). Covered w/75 sx plug; did not hold. Pmp'd 75 sx w/top @ 1183 7/18/75, held ok. Spt'd 20 sx @ top of 9-5/8" and installed abandonment marker 7/18/75.

18. I hereby certify that the foregoing is true and correct

SIGNED

J. W. Brunel

TITLE Div. Ops. Engr.

DATE 7/30/75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

cc: Oil & Gas Conservation Commission - Santa Fe, N.M.
Southern Pueblo Agency

*See Instructions on Reverse Side