

**WELL LOG**

Operator Harry C. Long, Operator Field Valencia County New Mexico 1938  
C.C.  
 Well No. "Dallier" 1 Sec. 32, T. 2N, R. 1E, N.M.P.M. B. & M.

Date	Bottom of Formation	DESCRIPTION
May 6, 1938		<u>Core No. 18 6030 - 6037 Rec. 5 of 10</u>
		Same lithology
	6069	Sand drilled with center bit
		<u>Core No. 19 6069 - 6079 Rec. 3 of 10</u>
		Same lithology
		Son Schlumberger Electric log and took sidewall samples as follows:
		5312 Sand, white, loose, medium to coarse grained
		4250 Sand, reddish brown, clayey, medium to coarse grained, fairly well sorted
		4199 Sand as above
		4043 Sand, as 4250 but more clayey and finer grained
		3120 Sand, muddy, gray, loose, medium grained, clayey, silty, dirty
		2925 Sand, reddish brown, loosely compact, medium grained clayey, silty
		2496 Sand, muddy gray, as 3/20 but finer
		2420 Sand, tan, compact, very clayey and silty, fine to medium
		2374 Sand as 2496 but coarse grained
6		Drilling suspended.
14		65 sacks of cement were pumped in and equalized through drill pipe hung at 1445'
15		Located top of cement at 1514'. Filled top 12' of surface casing with cement and placed 4" pipe marker
		Well abandoned in this condition

**ILLEGIBLE**