

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company : LIME ROCK RESOURCES II-A, LP	Contact : Mike Barrett
Address : 1111 Bagby Street Suite 4600, Houston, TX 77002	Telephone No. : 575-623-8424
Facility Name : West Red Lake #41	Facility Type: West Red Lake Unit Water Station #1

Surface Owner : BLM	Mineral Owner: BLM	Lease No. : API #30-015-28443
---------------------	--------------------	-------------------------------

**LOCATION OF RELEASE**

Unit Letter B	Section 7	Township 18S	Range 27E	Feet from the 330'	North/South Line FNL	Feet from the 1800'	East/West Line FEL	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	------------------------	-----------------------	-------------

Latitude 32.76852 N Longitude -104.31437 W

**NATURE OF RELEASE**


Type of Release : Produced Fluids (70% PW & 30% OIL)	Volume of Release : 1685 bbls	Volume Recovered: 560 bbls recovered from containment & 1200 bbls recovered from Pecos River on 5/27/13
Source of Release : Alarm malfunction & secondary containment failure	Date and Hour of Occurrence: 5/26/13 am	Date and Hour of Discovery: 5/27/13 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM, OCD, State Police, EPA	
By Whom? Mike Barrett w/LRR	Date and Hour : 5/27/13 @ 7:00 am	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse, 563 bbls	

If a Watercourse was Impacted, Describe Fully.\* Produced fluids exited location and flowed down the draw into the Pecos River for approximately 3 miles.

Describe Cause of Problem and Remedial Action Taken.\* The alarm malfunctioned causing tanks to overflow into secondary containment. The secondary containment failed causing the release of produced fluids to flow 1/2 mile down the draw into the Pecos River. All wells were shut in, the alarm was replaced and the impacted flow path in the draw was flushed with fresh water into lined pit at the bottom. Vacuum trucks (11) were immediately called to the location on 5/27/13. A berm was constructed at the bottom of the draw.

Describe Area Affected and Cleanup Action Taken.\* 1/2 mile down the draw and approximately 3 miles of the Pecos River was effected. Vac trucks were called to the location and west side of river. Sorbent booms were stretched across the river in 4 places, oil skimmers were used to recover free product and impacted water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Michael Barrett		Approved by District Supervisor:	
Title: Production Supervisor		Approval Date:	Expiration Date:
E-mail Address: mbarrett@limerockresources.com		Conditions of Approval:	
Date: 5/29/2013 Phone: 575-623-8424		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary