

From: [David Adkins](#)
To: [Bratcher, Mike, EMNRD](#); [Amos, James](#); [Hughes, Solomon](#); [Patterson, Heather, EMNRD](#)
Cc: [Michael Barrett](#); [Jerry Smith](#)
Subject: lab results, Lime Rock West Red Lake 13
Date: Friday, August 15, 2014 4:58:03 PM
Attachments: H402404 TALON.PDF

All,

Attached please find the lab report for the rain water samples obtained from the catch basin located at the bottom of this flow path in the ravine. As shown, the Total Petroleum and Volatile Organic concentrations were below laboratory method detection limits. Total Chloride results were 510 mg/liter.

Therefore, on behalf of Lime Rock Resources we respectfully request permission to remove this constructed catch basin and close out this incident. I will submit a Final C-141 to the OCD and BLM for this project next week. Please let me know if you have any questions. Thank you.

Respectfully,

David J. Adkins

District Manager

Talon/LPE

408 West Texas Avenue

Artesia, New Mexico 88210

(575) 746.8768 phone

(575) 746.8905 fax

(575) 441.4835 cell

Email: dadkins@talonlpe.com

Web: www.talonlpe.com

