

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

OCT 03 2014

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Mewbourne Oil Company	Contact	Zach Thomas
Address	P.O. Box 5270 Hobbs, NM 88241	Telephone No.	575-393-6862
Facility Name	Wyatt Draw 13 PA #001H	Facility Type	Oil Well

Surface Owner	State of New Mexico	Mineral Owner		API No.	30-015-40301
---------------	---------------------	---------------	--	---------	--------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	24	19S	25E	190	N	970	E	EDDY

Latitude 32.65296 Longitude -104.43297

### NATURE OF RELEASE

Type of Release	Oil	Volume of Release	25bbl	Volume Recovered	15bbl
Source of Release	Production Tank	Date and Hour of Occurrence	8/7/14	Date and Hour of Discovery	8/7/14
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required				
By Whom?	If YES, To Whom?				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
Date and Hour					
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Casing valve left open by accident allowing fluid to come to surface and leak into cellar and onto location. Well was shut off when discovered and casing valve was closed. Well left down overnight." The area affected is the pad surface around wellhead. Vacuum truck picked up all standing fluid (15bbl) and hauled to Fairchild SWD.

Describe Area Affected and Cleanup Action Taken.\*

Contaminated soil was excavated and hauled to NMOCD approved disposal site. All remedial activities were conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases. Vertical and horizontal delineation samples were taken and analysis run for TPH and BTEX (chlorides for documentation). The initial analytical results for TPH and BTEX were under RRAI's (site ranking is 20)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>3. Thomas</u>	OIL CONSERVATION DIVISION		
Printed Name: <u>Zach Thomas</u>	Approved by Environmental Specialist:		
Title: <u>Environmental Rep.</u>	Approval Date: <u>10/31/2014</u>	Expiration Date: <u>NA</u>	
E-mail Address: <u>zthomas@mewbourne.com</u>	Conditions of Approval:		Attached <input type="checkbox"/>
Date: <u>10-3-14</u>	Phone: <u>575-602-2188</u>	FINAL	

\* Attach Additional Sheets If Necessary

2RP-2426