

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Rec'd NMOCD Dist 2

11/5/14

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG Operating LLC	Contact	Robert McNeil
Address	600 West Illinois Avenue, Midland, Texas 79701	Telephone No.	(432) 230-0077
Facility Name	Salada Vista 36 State #2	Facility Type	Well Pad

Surface Owner: State	Mineral Owner	Lease No. (API#)30-015-40253
----------------------	---------------	------------------------------

LOCATION OF RELEASE

Unit Letter D	Section 31	Township 19S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County EDDY
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32 37.354° Longitude W 103 54.997°

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release 15 bbls oil 5 bbls of produced water	Volume Recovered 5bbls oil 0 bbls of produced water
Source of Release Hammer Union	Date and Hour of Occurrence 01-09-2014	Date and Hour of Discovery 01-09-2014 12:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A


Describe Cause of Problem and Remedial Action Taken.*

Hammer union started leaking on the wellhead. Replaced the hammer union.

Describe Area Affected and Cleanup Action Taken.*

Initially 15 bbls of oil and 5 bbls of produced water were released. 5 bbls of oil and 0 bbls of produced water were recovered with a vacuum truck. Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Ike Tavarez	Approved by District Supervisor:		
Title: Senior Project Manager, P.G.	Approval Date: 11/5/14	Expiration Date: N/A	
E-mail Address: ike.tavarez@tetrattech.com	Conditions of Approval: N/A Final		Attached <input type="checkbox"/>
Date: 7-16-14	Phone: (432) 687-8110		

* Attach Additional Sheets If Necessary

2RP-2169