

From: [Bratcher, Mike, EMNRD](#)
To: [Patterson, Heather, EMNRD](#)
Subject: FW: Dorado 34 DA Fed Com #1H
Date: Tuesday, December 09, 2014 11:37:33 AM
Attachments: image001.png
Dorado 34 DA Fed Com #1H Spill-Sample diagram.docx
Dorado 34 DA Soil Sample Results.pdf
C141- Dorado 34 DA Fed Com #1H (11-1-14) Final.pdf

From: Zack Thomas [mailto:zthomas@mewbourne.com]
Sent: Tuesday, December 09, 2014 8:35 AM
To: 'Whitlock, Jerald'; Bratcher, Mike, EMNRD
Subject: Dorado 34 DA Fed Com #1H

Gentlemen,

Attached is the final C-141 for the Dorado 34 DA Fed Com #1H. All visibly contaminated soil was removed from 2 inches up to 10 inches in the worse areas. Three samples were taken at 2' bgs and came back clean. Sample diagram is also attached. Based upon soil sample analytical Mewbourne Oil Company requests closure of this site. If you have any questions or concerns please feel free to call or email me.

Thanks,



Zack Thomas
Environmental Rep.
Mewbourne Oil Company
[PO Box 5270](#)
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252
(575) 602-2188
Email: zthomas@mewbourne.com