

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 12/15/2014

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Corral Draw #2	Facility Type	SWD
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-21425

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	22	25S	29E	1580	South	1980	West	Eddy County, NM

Latitude N 32.11249° Longitude W 103.97449°

NATURE OF RELEASE

Type of Release	Skim oil and Produced water	Volume of Release	Unknown	Volume Recovered	0 bbls
Source of Release	Pumps and Flow lines	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, NMOCD and Jennifer VanCuren, BLM		
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Various leaks caused by pumps and flow lines on this site have caused an unknown amount of skim oil and produced water to leak onto the ground. No fluids were recovered and pumps and flow lines have been repaired or replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected areas are inside the lined battery around the tanks (35' x 105'), Northeast of the lined battery around a pump (14' x 32'), Northwest of the lined battery just west of the drum (48' x 85'), and further Northwest of the battery near the road traveling off location (200' x 35'). Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 09/18/2014 and approved by Sol Hughes of the BLM via email on 08/29/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Chancey Summers	Approved by Environmental Specialist:		
Title: HES Advisor	Approval Date: 12/22/2014	Expiration Date: NA	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 12-9-14	Phone: (575) 397-8216	FINAL	

* Attach Additional Sheets If Necessary

2RP-2208