

District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 811 S. First St., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources  
 Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Form C-141  
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
 accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-276	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-35137
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	13	24S	29E	1980	North	1980	East	Eddy

Latitude: N 32.219375° Longitude: W 103.935907°

**NATURE OF RELEASE**

Type of Release: crude oil and produced water	Volume of Release: 4 bbls crude oil and 2 bbls produced water	Volume Recovered: 1 bbl oil
Source of Release: Wellhead stuffing box	Date and Hour of Occurrence: 11/3/14 @ unknown	Date and Hour of Discovery: 11/3/14 @ approx. 6:50 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.\* Not Applicable

Describe Cause of Problem and Remedial Action Taken.\*

The wellhead stuffing box packing failed, the unit was equipped with an e-pot designed to shut down the unit if the packing failed, the system operated properly, however gas pressure continued to blow product from the wellhead. The packing was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The spill impacted approximately 1,740 sq. ft. of pasture with a fine mist of oil and approximately 2,400 sq. ft. of caliche well pad with a mist of oil and saturated soil. The misted pasture area was washed down with soap, water and micro-blaze. The free standing fluid was picked up with a vacuum truck. Soil samples were collected, analyzed and based on laboratory analytical results the release area has been excavated and contaminated soil hauled to a state approved disposal facility. The excavation has been backfilled with clean soil. The area has been remediated in accordance with the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist:	
Printed Name: Bradley Blevins	Approval Date: 1/28/2015	Expiration Date: NA
Title: Assistant Remediation Foreman	Conditions of Approval:	
E-mail Address: bblevins@basspet.com	FINAL	Attached <input type="checkbox"/>
Date: 12-22-14 Phone: 432-214-3704		

\* Attach Additional Sheets If Necessary

2RP-2600