

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 3/16/2015  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Pure Gold A Federal #5	Facility Type	Well location
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-35292

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	21	23S	31E	2040	South	1980	West	Eddy County, NM

Latitude N 32.28827° Longitude W 103.78489°

**NATURE OF RELEASE**

Type of Release	Oil and produced water	Volume of Release	15 bbls oil, 20 bbls water	Volume Recovered	0 bbls
Source of Release	Stuffing box leak on well head	Date and Hour of Occurrence	07/17/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, NMOCD and Sol Hughes, BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	07/18/2014 @ 9:25 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The packing in the stuffing box on the well head was compromised and leaked 15 bbls of oil and 20 bbls of produced water onto the ground. No fluids were recovered and the packing in the stuffing box was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 150' x 40' both on and off location. The leak is mostly on the pad around and south of the well head with some overspray reaching into the pasture on the north side of the location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 11/04/2014 and approved by Sol Hughes of the BLM via email on 10/30/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Christopher Jones	Approved by Environmental Specialist:		
Title: HES Specialist	Approval Date: 3/17/2015	Expiration Date: N/A	
E-mail Address: <a href="mailto:christopher_jones@oxy.com">christopher_jones@oxy.com</a>	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 3/5/15	Phone: (575) 628-4121	<b>FINAL</b>	

\* Attach Additional Sheets If Necessary

2RP-2432