

From: [Lupe Carrasco](#)
To: [Patterson, Heather, EMNRD](#); [Bratcher, Mike, EMNRD](#)
Cc: [Amanda Trujillo](#); [Garrett Merket](#)
Subject: (Closure) GJ West COOP #92 Battery (2RP-2641)
Date: Thursday, March 19, 2015 8:08:39 AM
Attachments: (Closure)GJ West Coop #92 Battery.pdf

Mrs. Patterson,

Attached for your consideration is a closure request for the GJ West Coop #92 Battery release. Please feel free to contact me with any questions or concerns.

Thanks!

Lupe Carrasco

Environmental Coordinator

Concho Resources

Cell: [575.725.0787](tel:575.725.0787)

Office: [575.748.6933](tel:575.748.6933)

gcarrasco@concho.com

[2208 W. Main St.](#)

[Artesia, NM 88210](#)

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]
Sent: Thursday, March 05, 2015 1:42 PM
To: Lupe Carrasco; Bratcher, Mike, EMNRD
Cc: Amanda Trujillo; Garrett Merket
Subject: RE: (Work Plan) GJ West COOP #92 Battery

RE: COG * GJ West Coop #92 Battery * fAB1434354066 * 2RP-2641

Lupe,

Your work plan is approved with the following exception, the OCD would like to see the pad area also excavated at this time. A two foot excavation should suffice and may be backfilled immediately. The narrow flow path across the pad may be left in place to allow any necessary truck access.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Heather Patterson
Environmental Specialist
NMOCD District II
(575)748-1283 ext.101

From: Lupe Carrasco [<mailto:GCarrasco@concho.com>]
Sent: Tuesday, March 03, 2015 5:20 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Amanda Trujillo; Garrett Merket
Subject: (Work Plan) GJ West COOP #92 Battery

Mr. Bratcher/Mrs. Patterson,

Attached for your consideration is a Work Plan for the GJ West Coop Unit #92 Battery release that occurred on December 3, 2014. Please let me know if you have any questions or concerns.

Thanks!

Lupe Carrasco

Environmental Coordinator
Concho Resources
Cell: [575.725.0787](tel:575.725.0787)
Office: [575.748.6933](tel:575.748.6933)
gcarrasco@concho.com

[2208 W. Main St.](#)
[Artesia, NM 88210](#)

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Lupe Carrasco
Sent: Friday, November 21, 2014 1:18 PM
To: mike.bratcher@state.nm.us
Cc: 'Heather.Patterson@state.nm.us'
Subject: (Notification)GJ West COOP #92 Battery

Mr. Bratcher,

COG Operating LLC is reporting a release on the GJ West Coop #92 Battery
Section 28, Township 17S Range 29E
The release occurred at 8:00 am on 11/20/2014
Released: 9 bbls Oil, 24 bbls Produced Water
Recovered: 8 bbls Oil, 20 bbls Produced Water

The release was caused by a gasket failure on the fire tube of the heater treater. The release impacted the location and the surrounding pasture with the majority of the fluid release contained within the lined facility. The site is being evaluated for clean-up and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thanks!

Lupe Carrasco

Environmental Coordinator
Concho Resources
Cell: [575.725.0787](tel:575.725.0787)
Office: [575.748.6933](tel:575.748.6933)
gcarrasco@concho.com

[2208 W. Main St.](#)
[Artesia, NM 88210](#)

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.