

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <i>Enterprise Field Services LLC</i>	Contact <i>Dina Ferguson</i>
<i>PO Box 4324, Houston, TX 77210</i>	Telephone No. <i>210-528-3824</i>
Facility Name <i>Pipeline ROW, 1002 Gathering Lateral</i>	Facility Type: <i>Gas Gathering Pipeline</i>
Surface Owner <i>Private Owner</i>	Mineral Owner <i>NA - Pipeline</i>
	Lease No. <i>NA</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>NENE</i>	<i>26</i>	<i>24S</i>	<i>28E</i>	<i>125</i>	<i>South</i>	<i>325</i>	<i>West</i>	<i>Eddy</i>

Latitude: *N 32.192564* Longitude: *W -104.052654*

NATURE OF RELEASE

Type of Release <i>Natural Gas, Pipeline Liquids</i>	Volume of Release: <i>224 MCF, 1 BBL Liquids</i>	Volume Recovered: <i>N/A</i>
Source of Release <i>Pipeline Leak</i>	Date and Hour of Occurrence <i>11/08/2014 @ 12:23 MST</i>	Date and Hour of Discovery <i>11/08/2014 @ 12:23 MST</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <i>Pipeline leak was detected by a pumper passing by. Pipeline segment was isolated and blown down, and leaking portion was repaired.</i>		
Describe Area Affected and Cleanup Action Taken.* <i>Liquid spill occurred within pipeline ROW. Contaminated soil was excavated and disposed of at an approved landfill. Soil sampling demonstrates that TPH and BTEX concentrations are below NMOCD remediation levels. Due to naturally occurring chlorides in the area, background concentration samples were pulled to demonstrate that background chloride concentrations are over the NMOCD remediation action levels. The attached report provides full evaluation of the samples collected, soil conditions and field activities completed to demonstrate all remaining chlorides are due to naturally occurring chlorides. Excavation was backfilled with clean soil.</i>		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: <i>Jon E. Fields</i>	Approved by District Supervisor:	
Title: <i>Director, Field Environmental</i>	Approval Date: <i>7/14/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>jefields@eprod.com</i>	Conditions of Approval: <i>See attached notation</i>	Attached <input checked="" type="checkbox"/>
Date: <i>7-13-2015</i> Phone: <i>713-381-6684</i>		

* Attach Additional Sheets If Necessary

2RP-2905