

From: [Bockisch, Bernie](#)
To: [Bratcher, Mike, EMNRD](#)
Cc: [Zane Kurtz](#)
Subject: RE: Elk Wallow 11#3 1RP-3318 (Corrected: 2RP-2301)
Date: Friday, September 19, 2014 9:08:54 AM

Mike,

Thanks for reviewing so quickly. We'll get the Final C-141 report out to you.

Bernie

Bernard Bockisch, PMP
Conestoga-Rovers & Associates (CRA)

6121 Indian School Rd NE Ste. 200

Albuquerque, NM, USA 87110

Office: (505) 884-0672

Mobile: (505) 280-0572

Fax: (505) 884-4932

Email: bbockisch@croworld.com

www.CRAworld.com

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]
Sent: Thursday, September 18, 2014 3:56 PM
To: Bockisch, Bernie
Cc: Zane Kurtz
Subject: RE: Elk Wallow 11#3 1RP-3318 (Corrected: 2RP-2301)

RE: EOG Resources * Elk Wallow 11 St. 003H * 30-015-37590 * B-11-25s-29e * Eddy County, New Mexico

NMOCD Reference Number: **2RP-2301** * Date of release: 5/7/2014

Bernie,

Based on work performed and analytical data presented, NMOCD requires no further action for the above referenced release, other than submittal of closure report/Form C-141 Final Report. Please note the corrected RP number and county. The correction is the result of a data entry error on OCD's part and wrong county listed on the initial C-141.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, please contact me.

Thanks,

Mike Bratcher

NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Bockisch, Bernie [<mailto:bbockisch@croworld.com>]
Sent: Tuesday, September 16, 2014 1:05 PM
To: Bratcher, Mike, EMNRD
Cc: Zane Kurtz
Subject: Elk Wallow 11#3 1RP-3318

Mike,

On behalf of EOG Resources (EOG), please find a report summarizing the findings of a subsurface assessment performed at the above referenced site. A release of crude oil occurred during an upset condition from the on-site flare (see attached C-141). Impacted soil was excavated and the excavation was backfilled with clean soil. Conestoga Rovers and Associates staff collected soil samples using a hand auger and submitted them for laboratory analysis of petroleum hydrocarbons and chlorides. The analytical results were below New Mexico Oil Conservation Division Risk Ranking Action Levels. Based on this, EOG is requesting that no further action be required for this site. Please feel free to contact me if you have any questions.

Bernie

Bernard Bockisch, PMP
Conestoga-Rovers & Associates (CRA)
6121 Indian School Rd NE Ste. 200
Albuquerque, NM, USA 87110
Office: (505) 884-0672
Mobile: (505) 280-0572
Fax: (505) 884-4932
Email: bbockisch@croworld.com
www.CRAworld.com

CRA and GHD have merged! To learn more, visit www.CRAworld.com/ghd