

Received 8/27/17

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico NMOCD Dist 2  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

nAB1517357601

## OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Jester 19/30 W2DE Fed Com #1H	Facility Type: Producing Oil Well

Surface Owner: NM State Land Trust	Mineral Owner: BLM	API No. 30-015-42831
------------------------------------	--------------------	----------------------

## LOCATION OF RELEASE

Unit Letter D	Section 19	Township 23S	Range 27E	Feet from the 185'	North/South Line North	Feet from the 660'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.297497 Longitude -104.1673659

## NATURE OF RELEASE

Type of Release: Hydrochloric Acid 15%	Volume of Release: 958 bbls	Volume Recovered: 800 bbls
Source of Release: Frac Tank	Date and Hour of Occurrence 6-18-15 2:30 am	Date and Hour of Discovery 6-18-15 2:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos (BLM)	
By Whom? Zack Thomas	Date and Hour 6-18-15 10:15 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

Cause of leak: A frac tank containing 15% hydrochloric acid had a hole releasing 958 bbls onto the pad surface.

Describe Area Affected and Cleanup Action Taken.\*

The pad surface was the only area affected. Acid was neutralized using Soda Ash and natural caliche. Backhoes and vacuum trucks were used to push and recover the 800 bbls of neutralized acid. All visually contaminated material was picked up and hauled off to an NMOCD approved disposal facility. Soil samples were taken to confirm PH levels. Final remediation was conducted in accordance with BLM and the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Zack Thomas	Approved by Environmental Specialist:	
Title: Environmental Rep.	Approval Date: 9/2/15	Expiration Date: N/A
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 8-27-15 Phone: 575-602-2188	FINAL	

\* Attach Additional Sheets If Necessary

2RP-3061