

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 6/11/2015

NMOCD Artesia

Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Memorial Production Operating LLC	Contact: Heather Dolphin	
Address: 500 Dallas Street Houston TX 77002	Telephone No.: 832-797-1334	
Facility Name: North Square Lake Unit #154 2RP-2982	Facility Type: Well	
Surface Owner:	Mineral Owner:	API No.: 30-015-04986

LOCATION OF RELEASE

Unit Letter F	Section 34	Township 16S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: 32.879576 Longitude: -103.860639

NATURE OF RELEASE


Type of Release: Oil	Volume of Release: 7 bbl.	Volume Recovered: 2 bbl.
Source of Release: 2" Steel Flowline	Date and Hour of Occurrence: 4/29/15	Date and Hour of Discovery: 11:35
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM	
By Whom? Heather Dolphin	Date and Hour 4/30/15	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. n/a	

If a Watercourse was Impacted, Describe Fully.*: n/a

Describe Cause of Problem and Remedial Action Taken.*: The 2" steel flow line going from the NSLU #154 to the battery developed a pin hole approximately 60 yards off location and out in the field. It spilled approx. 7 bbl. of oil.

Describe Area Affected and Cleanup Action Taken.*: 2 bbl. were recovered by vac. truck. A clamp was put on the pipe to cover the hole. Etech Environmental excavated impacted soil and disposed of soil to Lea Land. Confirmation samples were collected to ensure excavated area was below state's threshold levels. Site was backfilled and topdressed with surrounding soil for reseeded to complete reclamation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Tim McMinn	Approved by District Supervisor:		
Title: Etech Environmental	Approval Date: 11/9/2015	Expiration Date: N/A	
E-mail Address: tim@etechenv.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: 11/6/15	Phone: 432-967-9062		

* Attach Additional Sheets If Necessary

2RP-2982