

## Bratcher, Mike, EMNRD

---

**From:** Blevins, Bradley G <Bradley.Blevins@chevron.com>  
**Sent:** Wednesday, March 05, 2014 10:58 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Blevins, Bradley G  
**Subject:** Skelly 952  
**Attachments:** GPS.jpg; H302908 EPI.pdf; Skelly 952 Initial C-141.pdf

Mike,

If you recall this is the release we talked about at Linn Energy's office where the contractor struck our water line. Upon reviewing the sample data Chevron would like to remove one foot of soil from the release area and backfill with clean topsoil. We would like to proceed with the cleanup and would appreciate your approval/ comments with this proposal. If you have any questions please give me a call.

Thank You,



Bradley Blevins  
Chevron Delaware Basin  
HES Specialist  
Hobbs FMT  
Direct 575-391-1462 86424  
Cell- 575-441-0341