Submit 1 Copy To Appropriate District Office	State of New Mexico			Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO. 30-015-21650	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III – (505) 334-6178	1220 South St. Francis Dr.		STATE STEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM	s Dr., Santa Fe, NM		LC-5669	
87505 SUNDRY NOTI	CES AND REPORTS ON WELLS	5/10-17	7. Lease Name or Unit Ag	reement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Myrtle Myra	
1. Type of Well: Oil Well Gas Well Other Plugged well			8. Well Number 8	
2. Name of Operator			9. OGRID Number	
Endurance Resources LLC			270329	
3. Address of Operator P. O. Box 1466 – Artesia, NM 88211-1466			10. Pool name or Wildcat SWD	
4. Well Location				
	om North line and 1980 feet from th	ne East line		
Section 16 Township 21S Range 27E NMPM Eddy County				
The state of the s	11. Elevation (Show whether DR,			
12. Check A	Appropriate Box to Indicate N		•	
			SSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WOR			
TEMPORARILY ABANDON	<del>-</del>		RILLING OPNS. P AND A	Α 📗
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN		II JOB	
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM	OTHER: Extra remed		remedial work performed	Х
OTHER:				
13. Describe proposed or comp of starting any proposed wo proposed completion or rec	leted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC ompletion.	pertinent details, ar C. For Multiple Co	nd give pertinent dates, includ ompletions: Attach wellbore of	ling estimated date diagram of
OCD required that extra remedial work be performed on this location. There was a berm barrier wall on location that needed to be pushed down and levelled.				
Berm barrier wall was pushed down and levelled into location. Pictures are attached. Work was completed on May 5, 2016.				
2 3 cannot be a second and a second and a second a s				
Spud Date: Rig Release Date:				
•	_			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE FUNCE THE TITLE HAVE Manger, Phiduchamate May 19, 2016				
Type or print name RUSTY KLEIN E-mail address: rusty@enduranceresourcesllc.com PHONE: 575-308-0722/575-703-6412				
Type or print name RUSTY KLEIN	E-mail address: rusty@enduranc	eresourcesiic.com	FHUNE: 3/3-308-0/22/3/3	-/03-0412
For State Use Only				
APPROVED BY:	TITLE		DATE	
Conditions of Approval (if any):				



