

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Dusty Wilson
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5771
Facility Name	Lost Tank 35 State #1 SWD Facility	Facility Type	Battery

Surface Owner	State	Mineral Owner	API No. 30-015-40890
---------------	-------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	35	21S	31E					Eddy County, NM

Latitude N 32.43482° Longitude W 103.74899°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	18 bbls	Volume Recovered	15 bbls
Source of Release	Corrosion of nipple on the discharge line	Date and Hour of Occurrence	09/08/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Brucher, Heather Patterson- NMOCD			
By Whom?	Kathy Purvis, BBC International	Date and Hour	09/08/2015 @ 3:27 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Internal corrosion of a steel nipple on the discharge line caused 18 bbls of produced water to leak onto the ground. A vacuum truck recovered 15 bbls of water and the nipple was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is inside the lined battery. Remediation will be completed by removing the impacted soil from the lined battery and replacing it with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Dusty Wilson

Title: Environmental Advisor

E-mail Address: Dusty.Wilson@oxy.com

Date: 9/21/15

Phone: (432) 685-5771

Approved by Environmental Specialist:

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Lost Tank 35 State #1 SWD Facility	Facility Type	Battery
Surface Owner	State	Mineral Owner	API No. 30-015-40890

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	35	21S	31E					Eddy County, NM

Latitude N 32.43482° Longitude W 103.74899°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	18 bbls	Volume Recovered	15 bbls
Source of Release	Corrosion of nipple on the discharge line	Date and Hour of Occurrence	09/08/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	09/08/2015 @ 3:27 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Internal corrosion of a steel nipple on the discharge line caused 18 bbls of produced water to leak onto the ground. A vacuum truck recovered 15 bbls of water and the nipple was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is inside the lined battery. Remediation was completed by removing the impacted soil from the lined battery and replacing it with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Casey Summers	Approved by Environmental Specialist:		
Title: NM Environmental Advisor	Approval Date:	Expiration Date:	
E-mail Address: Casey_Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7-11-10	Phone: (575) 513-8289		

* Attach Additional Sheets If Necessary



Groundwater Plot

Oxy Lost Tank 35 State #1 SWD Facility

County
Eddy


Unit Letter
K

Section
35

Township
21S

Range
31E

Trend Map 125'-150'



📍 Location

● OCD

● USGS

● SEO

● All Databases



09/10/2015

