

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 7/13/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	MOC SWD Well Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	API No. 30-015-21669

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	7	20S	25E					Eddy

Latitude N 32.58654° Longitude W 104.52686°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	50 bbls	Volume Recovered	25 bbls
Source of Release	Holes in bottom of tank	Date and Hour of Occurrence	02/04/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson-NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	02/05/2016 @ 1:53 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Holes in the bottom of tank caused a leak of 50 bbls of oil. A vacuum truck recovered 25 bbls of oil and the holes were repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 25' x 100' on location inside the containment. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 03/17/2016 and Arthur Arias of the BLM via email on 03/17/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Casey Summers		Approved by Environmental Specialist:	
Title: NM Environmental Advisor		Approval Date: 7/14/2016	Expiration Date: N/A
E-mail Address: Casey_Summers@oxy.com		Conditions of Approval:	
Date: 7-11-16 Phone: (575) 513-8289		FINAL	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-3556