RE: BopCo * PLU 261 * 30-015-34877 * 2RP-1012 * 2RP-2333 * 2RP-2957

Brad,

Your closure request for the above listed location is approved.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Blevins, Bradley [mailto:BBlevins@BassPet.Com]
Sent: Friday, July 08, 2016 10:05 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: PLU 261 Closure Report

Mike/ Heather

Please find the attached closure report for the PLU 261 battery, if you have any questions please let me know. Thank you

Brad Blevins BOPCO, LP 522 W. Mermod, Suite 704 Carlsbad, NM 88220 Office-575-887-7329 Cell-1-432-214-3704 bblevins@basspet.com