

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

| | |
|---|-----------------------------|
| Name of Company: Linn Energy | Contact: EL Gonzales |
| Address: 2130 W Bender, Hobbs, NM 88240 | Telephone No. 575-738-1739 |
| Facility Name: JL Keel A #020 | Facility Type: Oil Producer |
| Surface Owner: Federal | Mineral Owner: Federal |
| API No. 30-015-28059 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|-----------|----------------|--------|
| B | 7 | 17S | 31E | 200 | North | 1480 | East | Eddy |

Latitude: 32° 51' 20.38" N Longitude: 103° 54' 19.39" W

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release: Oil | Volume of Release: 1 bbl | Volume Recovered: 0 bbl |
| Source of Release: Stuffing Box | Date and Hour of Occurrence | Date and Hour of Discovery 01/05/2011 |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? NMOCD | |
| By Whom? Kimberly Wilson | Date and Hour: 01/05/2011 | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Stuffing box leak. Removed contaminated dirt and exported. Re-packed stuffing box.

Describe Area Affected and Cleanup Action Taken.

The contaminated soil was removed from the site and properly disposed of at a NMOCD approved facility. The excavation was backfilled with clean, imported soil to ground surface and contoured to the surrounding area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|---------------------------------------|-----------------------------------|
| Signature:  | OIL CONSERVATION DIVISION | |
| Printed Name: EL Gonzales | Approved by Environmental Specialist: | |
| Title: Production Supervisor | Approval Date: 8/8/2016 | Expiration Date: N/A |
| E-mail Address: elgonzales@linenergy.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 7/25/2016 Phone: 575-504-8002 | FINAL | |

* Attach Additional Sheets If Necessary