

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
**District II**  
1301 W. Grand Avenue, Artesia, NM 88210  
**District III**  
1000 Rio Brazos Road, Aztec, NM 87410  
**District IV**  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

NMOCD Dist 2

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

fAB1534852873

**Release Notification and Corrective Action**

nAB1534853014

**OPERATOR**
☐ Initial Report ☒ Final Report

Name of Company <b>Enterprise Field Services LLC</b>	Contact <b>Alena Miro</b>
<b>PO Box 4324, Houston, TX 77210</b>	Telephone No. <b>575-706-4926</b>
Facility Name <b>Pipeline ROW, Chinaberry Line</b>	Facility Type: <b>Gas Gathering Pipeline</b>
Surface Owner <b>BLM</b>	Mineral Owner <b>NA - Pipeline</b>
Lease No. <b>NA</b>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>P</b>	<b>5</b>	<b>23S</b>	<b>26E</b>	<b>505</b>	<b>North</b>	<b>105</b>	<b>West</b>	<b>Eddy</b>

Latitude: N 32.328537 Longitude: W -104.310943

**NATURE OF RELEASE**

Type of Release <b>Natural Gas and Pipeline Liquids</b>	Volume of Release: <b>194 MCF gas and 9bbl liquids</b>	Volume Recovered: <b>N/A</b>
Source of Release <b>Pipeline Leak.</b>	Date and Hour of Occurrence <b>12/08/2015 @ 11:30 MST</b>	Date and Hour of Discovery <b>12/08/2015 @ 11:30 MST</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

**Pipeline leak was detected by a pipeline technician. Pipeline segment was isolated, blown down, and repaired following standard one-call. Approximately nine (9) bbls of liquid noted on ROW.**

Describe Area Affected and Cleanup Action Taken.\*

**A liquid spill of approximately nine (9) bbls occurred as part of the leak. Remediation actions followed the Enterprise Products, General Release Notification, Response and Remediation Plan (March 9, 2015).**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Jon E. Fields</b>	Approved by District Supervisor: <b>MBratcher</b>	
Title: <b>Director, Field Environmental</b>	Approval Date: <b>8/23/16</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>jefields@eprod.com</b>	Conditions of Approval: <b>N/A</b>	Attached <input type="checkbox"/>
Date: <b>8-19-2016</b> Phone: <b>713-381-6684</b>	<b>FINAL REPORT</b>	

\* Attach Additional Sheets If Necessary

2RP-3446