

Received 9/27/2016

NMOCD Artesia

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-230-0077
Facility Name: State 11 Com #001	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-27916
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	11	19S	28E	2310	South	660	East	Eddy County, NM

Latitude N 32.67448°

Longitude W 104.14102°

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 80 bbls	Volume Recovered: 80 bbls
Source of Release: Hole in tank	Date and Hour of Occurrence 07/15/2015 @ 11:34 am	Date and Hour of Discovery 07/15/2015 @ 11:34 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 07/17/2015 3:57 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


This release was caused by a hole in the tank. A vacuum truck was dispatched to recover all free-standing fluids.

Describe Area Affected and Cleanup Action Taken.*

This release was contained within the bermed area. The site was delineated and a remediation plan was developed. The remediation plan was approved by Mike Bratcher of NMOCD via email on 09/13/2016 and approved by Amber Groves of the SLO via email on 09/15/2016. Remediation was completed in accordance with the approved plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:



Printed Name: Robert Grubbs

Title: Senior Environmental Coordinator

E-mail Address: rgrubbs@concho.com

Date: September 23, 2016

Phone: (432) 683-7443

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date: 9/28/2016

Expiration Date: N/A

Conditions of Approval:

FINAL

Attached ☐

* Attach Additional Sheets If Necessary

2RP-3182