From: Zack Thomas

 To:
 Patterson, Heather, EMNRD

 Cc:
 Bratcher, Mike, EMNRD

 Subject:
 RE: Pine Box 17 AP Fed #1 2RP-2253

 Date:
 Thursday, October 06, 2016 11:49:01 AM

Attachments: image001.png

image002.png

Pine Box 17 AP Fed Com #1H Final Closure Report.pdf

Heather,

If you have any questions or concerns holler at me. Thank you

**Zack Thomas**Environmental Rep.

Mewbourne Oil Company PO Box 5270 Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252

(575) 602-2188

Email: zthomas@Mewbourne.com



From: Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]

Sent: Monday, September 26, 2016 9:35 AM

To: Zack Thomas

Cc: Bratcher, Mike, EMNRD

Subject: RE: Pine Box 17 AP Fed #1 2RP-2253

Zack,

We will need analytical results for this one, and a closure report. Do you know how deep the excavation went? If you could get samples at the excavation depth and just below to show it was fully cleaned up. Also, was the containment area lined? If not, we will need a delineation of that area.

Give me a call if you have any more questions.

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228 **From:** Zack Thomas [mailto:zthomas@mewbourne.com]

Sent: Thursday, September 22, 2016 9:48 AM

**To:** Patterson, Heather, EMNRD **Cc:** Bratcher, Mike, EMNRD

Subject: Pine Box 17 AP Fed #1 2RP-2253

Heather,

We hauled off all stained material from the pad surface as well as the reclaimed area (which was just overspray). However I can't find any sample data for this release. We have established good vegetation across the reclaimed area and the pad looks fairly good. I have attached some pictures of what the site looks like currently. Let me know what you think and what I should do for this. Thank you

**Zack Thomas** 

Environmental Rep. Mewbourne Oil Company PO Box 5270

Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252

(575) 602-2188

Email: <u>zthomas@Mewbourne.com</u>

