

**From:** Blevins, Bradley  
**To:** [Patterson, Heather, EMNRD](#)  
**Cc:** [Blevins, Bradley](#)  
**Subject:** PLU 347  
**Date:** Wednesday, October 19, 2016 11:01:44 AM  
**Attachments:** H602277 EPI.pdf  
scan.pdf

---

Heather

Attached is the initial C-141 and lab data for the release that occurred on the PLU 347. As stated in the initial notification we were able to dispatch a backhoe to the location the same day that the release occurred to remove the saturated surface soils. In reviewing the attached lab report BOPCO would like to request no further action on this location, if approved we will backfill the surface scraped areas and submit a closure report. Thank you

Brad Blevins  
BOPCO, LP  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office-575-887-7329  
Cell-1-432-214-3704  
[bblevins@basspet.com](mailto:bblevins@basspet.com)