

Bratcher, Mike, EMNRD

From: Tucker, Shelly <stucker@blm.gov>
Sent: Monday, October 17, 2016 9:42 AM
To: Patterson, Heather, EMNRD
Cc: Sheldon Hitchcock; Kimberly M. Wilson; Bratcher, Mike, EMNRD; Chris Morphew; jamest@daktoares.com
Subject: Re: Dakota Resources Trigg Fed 1

Sheldon,

BLM concurs with NMOCD approval to backfill your excavation site.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
O&G Spill/Release Coordinator

Bureau of Land Management
620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular
575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Wed, Oct 12, 2016 at 6:30 AM, Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us> wrote:



Sheldon,

You are approved to backfill this location.

Thank you,

Heather Patterson

Environmental Specialist

NMOCD District II

Office (575)748-1283 ext.101

Cell (575)703-0228

From: Sheldon Hitchcock [mailto:slhitchcock@talonlpe.com]

Sent: Tuesday, October 11, 2016 3:01 PM

To: Patterson, Heather, EMNRD; Kimberly M. Wilson

Cc: Bratcher, Mike, EMNRD; Tucker, Shelly; 'Chris Morpew'; jamest@daktoares.com

Subject: RE: Dakota Resources Trigg Fed 1

Heather, Shelly,

The TPH and BTEX results for the sidewalls around S-4 are attached. As you will see the North sidewall was above RRAL's during our first sample event. We extended that sidewall to the north another few feet and it is now clean. At this time I would like permission to backfill the excavation.

Respectfully,

Sheldon Hitchcock
Project Manager
Office: 575.746.8768
Direct: 575.616.4021
Cell: 575.689.5198
Fax: 575.746.8905
Emergency: 866.742.0742
Web: www.talonlpe.com



From: Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]
Sent: Friday, September 16, 2016 9:30 AM
To: Kimberly M. Wilson <kwilson@talonlpe.com>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Sheldon Hitchcock <shhitchcock@talonlpe.com>; David Adkins <dadkins@talonlpe.com>; Tucker, Shelly <stucker@blm.gov>
Subject: RE: Dakota Resources Trigg Fed 1

Kimberly,

Did you get the confirmation samples for S-4?

Heather Patterson

Environmental Specialist

NMOCD District II

Office (575)748-1283 ext.101

Cell (575)703-0228

From: Kimberly M. Wilson [<mailto:kwilson@talonlpe.com>]
Sent: Thursday, September 15, 2016 1:55 PM
To: Patterson, Heather, EMNRD
Cc: Bratcher, Mike, EMNRD; Sheldon Hitchcock; David Adkins
Subject: Dakota Resources Trigg Fed 1

RE: Dakota Resources * Trigg Fed 001 * 30-015-25006 * L-7-21s-28e * Eddy County, New Mexico

NMOCD Tracking Number: **2RP-1814** * Date of release: 8/16/2013

Heather,

Good afternoon. Attached is the site map for the above referenced location. Yesterday I pulled soil samples from the sidewalls (N, S, E) around sample location S-5. I performed field titration for chlorides on site. My results are as follows: North sidewall = 212 mg/kg, South sidewall = 567 mg/kg, East sidewall = 212 mg/kg

On behalf of our client, we would respectfully request permission to begin backfilling operations on this project.

If you have any questions or concerns please feel free to contact me. Thank you.

Kimberly M. Wilson

Project Manager

Office: 575.746.8768

Direct: 575.616.4023

Cell: 575.602.3826

Fax: 575.746.8905

Emergency: 866.742.0742

Web: www.talonlpe.com

