



June 7, 2016

Mike Bratcher
New Mexico Energy, Minerals & Natural Resources Oil Conservation Division,
Environmental Bureau - District 2
811 S. First St.
Artesia, NM 88210

RE: Corrective Action Plan
Burnett Oil Co., Inc. - Gissler B 5 Tank Battery
UL/O sec. 8 T17S R30E

Mr. Bratcher

The above location is located approximately 1 mile north of Loco Hills, New Mexico at UL/O sec. 8 T17S R30E. The site is located in an area of no known groundwater.

On March 6, 2016 a release was discovered of 60 barrels of crude oil. The release occurred when the check valve on the drain line failed. The release impacted a 205'x1' area in a pipeline ROW with a 10'x 30' pooling area in a pipeline ROW. There was also an impacted area of 60'x10' area on the facility location. The BLM and the NMOCD were both notified of the release on March 7, 2016 with the initial C-141 being filed on the same day.

Corrective Action Plan

To remediate the impacted soil, Burnett Oil Co., Inc. would like to work the impacted area with chloride bonding agents, flush the area with fresh water and drive the chlorides approximately 3' below surface level. After each installment of binding agents, Burnett Oil Co., Inc. will collect samples for verification of remediation success. Once the chlorides have been pushed below the root zone, and the hydrocarbons have been remediated below regulatory standards the area will be reseeded with BLM #2 seed mix. The area will then be observed until sufficient regrowth occurs.



June 7, 2016

Following the approval of the plan and after the remediation has taken place, Burnett Oil Co., Inc. will submit all proper closure documentation to the NMOCD and the BLM in accordance to the State and Federal Guidelines set forth.

Please feel free to contact me with any questions concerning this remediation plan request.

Sincerely,

Johnny Titsworth
HSE Coordinator
Burnett Oil Co., Inc.
P.O. Box 188 / CR 220 North
Loco Hills, NM 88255
(432)-425-2891
Email: jtitsworth@burnettoil.com