

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 12/7/2016  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

Initial Report ☐ X Final Report

Name of Company: Burnett Oil Co., Inc.	Contact: Johnny Titsworth	
Address: Burnett Plaza-Ste 1500, 801 Cherry St-Unit 9, Fort Worth, TX 76102	Telephone No. (432) 425-2891	
Facility Name: Gissler B 5 TB	Facility Type: Tank Battery	
Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-36271

### LOCATION OF RELEASE

Unit Letter O	Section 8	Township 17S	Range 30E	Feet from the 233	North/South Line FSL	Feet from the 1674	East/West Line FEL	County Eddy
------------------	--------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32.84250 Longitude: -103.99133

### NATURE OF RELEASE

Type of Release: oil	Volume of Release: 60 bbls	Volume Recovered: 40 bbls
Source of Release: check valve on drain failed	Date and Hour of Occurrence	Date and Hour of Discovery: 6/6/16
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM – S. Tucker OCD – H. Patterson	
By Whom? Leslie Garvis	Date and Hour: 3/7/16	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*  N/A		
Describe Cause of Problem and Remedial Action Taken.* Check valve on Drain failed. Repair was made and equipment was put back into service. Bio-remediation was performed to get with in regulatory levels.		
Describe Area Affected and Cleanup Action Taken.* Approx 60'x5' area on the pad, and 30'x10' and 205'x1' area in pipeline ROW/pasture.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Johnny Titsworth	Approved by Environmental Specialist: <i>Heather Patterson</i>	
Title: HSE Coordinator	Approval Date: 12/16/2016	Expiration Date: N/A
E-mail Address: jtitsworth@burnettoil.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/7/16 Phone: (432) 425-2891	FINAL	

\* Attach Additional Sheets If Necessary

2RP-3601