Bratcher, Mike, EMNRD

From: Michael Alves <malves@diversifiedfsi.com>

Sent: Thursday, January 5, 2017 12:07 PM

To: Bratcher, Mike, EMNRD; Laura Flores; Tucker, Shelly

Cc: Michael Burton; john_robinson@xtoenergy.com; Weaver, Crystal, EMNRD

Subject: RE: XTO - Nash Unit #042 H Work Plan

Attachments: H700027 DIVERSIFIED.PDF

Here is the results at 1' for all 4 sample points.

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]

Sent: Wednesday, January 04, 2017 2:31 PM

To: Laura Flores ! Tucker, Shelly <stucker@blm.gov

Cc: Michael Alves <malves@diversifiedfsi.com>; Michael Burton <mburton@diversifiedfsi.com>;

john robinson@xtoenergy.com; Weaver, Crystal, EMNRD < Crystal.Weaver@state.nm.us>

Subject: RE: XTO - Nash Unit #042 H Work Plan

RE: XTO Energy * Nash 42 CTB * 2RP-3976 * DOR: 10/17/16

Greetings,

Your proposal for remediation of the above referenced release is <u>not</u> approved. OCD concurs with BLM assessment that the site lacks adequate lab data to consider this proposal. OCD requests impacted gravel in the battery be removed, the liner inspected for holes, tears, etc., and clean gravel replaced. In the event the liner has been compromised, OCD is to be notified. If the liner is intact, photos are encouraged for documentation. Impacted areas outside the lined battery area will require at a minimum, lab data from samples obtained at 1' increments. A remedial proposal may then be considered based on actual data.

If you have any questions or concerns, please contact me.

Mike Bratcher NMOCD District 2 811 South First Street Artesia NM 88210 575-748-1283 Ext 108 mike.bratcher@state.nm.us

From: Laura Flores [mailto:lflores@diversifiedfsi.com]

Sent: Tuesday, December 6, 2016 10:41 AM

To: Bratcher, Mike, EMNRD < <u>mike.bratcher@state.nm.us</u>>; Tucker, Shelly < <u>stucker@blm.gov</u>> **Cc:** Michael Alves < <u>malves@diversifiedfsi.com</u>>; Michael Burton < <u>mburton@diversifiedfsi.com</u>>;

john robinson@xtoenergy.com

Subject: XTO - Nash Unit #042 H Work Plan

Good morning.

Attached is the Work Plan for the XTO Nash Unit #042H site.

Please let me know if you have any questions or comments.

Thank you,

Laura Flores Report Writer Environmental Department Diversified Field Service, Inc. 206 W Snyder | Hobbs, NM 88240

Phone: 575.964.8394 | Fax: 575.964.8396