

**From:** [Patterson, Heather, EMNRD](#)  
**To:** "Blaney, Karolina"  
**Cc:** [Bratcher, Mike, EMNRD](#); [stucker@blm.gov](mailto:stucker@blm.gov); [Crystal EMNRD Weaver \(Crystal.Weaver@state.nm.us\)](mailto:Crystal.EMNRD.Weaver@state.nm.us)  
**Subject:** RE: WPX RDU 61 - initial C-141  
**Date:** Thursday, November 17, 2016 10:54:00 AM  
**Attachments:** coa 3989.pdf

---

Karolina,

Please see the attached Conditions of Approval for the Initial C-141 spill report you sent on 11/12/2016. Your tracking number for this event is 2RP-3989.

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** Blaney, Karolina [mailto:[Karolina.Blaney@wpxenergy.com](mailto:Karolina.Blaney@wpxenergy.com)]  
**Sent:** Saturday, November 12, 2016 4:35 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'  
**Subject:** RE: WPX RDU 61 - initial C-141

Good afternoon,  
Attached is C-141 for the RDU 61 spill.  
Please let me know if you have any questions or concerns.  
Thank you,

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Blaney, Karolina  
**Sent:** Tuesday, November 01, 2016 2:19 PM  
**To:** 'Patterson, Heather, EMNRD' <[Heather.Patterson@state.nm.us](mailto:Heather.Patterson@state.nm.us)>; 'Bratcher, Mike, EMNRD' <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; 'stucker@blm.gov' <[stucker@blm.gov](mailto:stucker@blm.gov)>  
**Subject:** WPX RDU 61 - spill notification

Good afternoon,

On 10/30/16, WPX had a small spill at the RDU 61 well pad, API # 30-015-41980. Approximately 15 bbls of water and oil were spilled on location due to mechanical failure; stainless steel line between the wellhead and Murphy's switch failed. We recovered 10 bbls of water and 3 bbls of oil. The impacted area was mapped, scraped off, and sampled. Further remediation will depend on the lab

results. The C-141 report will be submitted within 15 days from the incident.  
Please let me know if you have any questions or concerns.  
Thank you and have a great afternoon,

*Karolina Blaney*

Environmental Specialist

WPX Energy

Cell: (970) 589-0743

[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)