

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1629842400

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	OWL 20504 JV-P #005	Facility Type:	Tank Battery

Surface Owner:	Federal	Mineral Owner:		API No.	30-015-35435
----------------	---------	----------------	--	---------	--------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	18	26S	27E	2310'	South	2310'	East	East

Latitude 32.0414886 Longitude 104.2282181

#### NATURE OF RELEASE

Type of Release:	Oil & Produced Water	Volume of Release:	2bbls Oil & 18bbls Produced Water	Volume Recovered:	1bbls Oil & 17bbls Produced Water
Source of Release:	PLC Control Valve	Date and Hour of Occurrence:	10-17-2016 11:30 am	Date and Hour of Discovery:	10-17-2016 11:30 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour:			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Facility operational control system (PLC) malfunctioned and failed to provide accurate operational data to alarms and system water stream control valve. Had the (PLC) repaired.

Describe Area Affected and Cleanup Action Taken.\*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment has been cleaned and the impacted gravel has been removed. Fresh gravel has been placed inside the containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>[Signature]</i>		
Title: Senior Environmental Coordinator	Approval Date: 2/22/17	Expiration Date: N/A	
E-mail Address: rhaskell@concho.com	Conditions of Approval: Containment cleaned Liner inspected		Attached <input type="checkbox"/>
Date: January 6, 2017	Phone: 432-683-7443		

\* Attach Additional Sheets If Necessary

2RP-3952