

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report

X Final Report

Name of Company Lime Rock Resources II-A, L.P.	Contact Mike Barrett	
Address R347-2 North 26 Street, Artesia, New Mexico 88210	Telephone No. 505-353-2644	
Facility Name ASAU 149 Trunk line release		
Surface Owner Fee	Mineral Owner State	API No. 30-015-00204

**LOCATION OF RELEASE**

Unit Letter O	Section 14	Township 18S	Range 26E	Feet from the 990	North/South Line FSL	Feet from the 1650	East/West Line FEL	County EDDY
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude 32.74266 Longitude 104.34846

**NATURE OF RELEASE**

Type of Release Hydrocarbon, produced waters. gas	Volume of Release unknown	Volume Recovered 0 bbls
Source of Release production line	Date and Hour of Occurrence 9/30/2016 am	Date and Hour of Discovery 9/30/2016 am
Was Immediate Notice Given? Yes No X Not Required as release was less than 5 bbls	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Full

B

Describe Cause of Problem and Remedial Action Taken.\*

A 3" below grade FG flow line developed a leak due to corrosion, the line was immediately shut-in, and the line was excavated and removed from service. The volume of the release caused by the below grade flow line was unknown.


Describe Area Affected and Cleanup Action Taken.\*

The area affected by the release is on the west side of Fanning road (CR-44) and was measured to be 15L'x15W'. The impacted material from the release was excavated and then transported to Lea Land LLC. Confirmation soil samples were collected from the excavated area and sent to Cardinal laboratories for analytical testing. Analytical testing results are attached. Based upon the Final Remediation Closure report dated February 24, 2017 Lime Rock Resources II-A, L.P. is requesting closure for the release at occurred on September 7, 2016 at the ASAU 149 Trunk line production line.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

AMENDED

Signature:



Printed Name: Michael Barrett

Title: Production Superintendent

E-mail Address: Michael Barrett <mbarrett@limerockresources.com>

Date: 2/24/2017

Phone: 505-353-2644

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary