

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1613042587

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Devon Energy Production	Contact Matt Nettles, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-513-5767
Facility Name Cotton Draw Unit 182H Battery	Facility Type Oil

Surface Owner State	Mineral Owner State	API No. 30-015-31889
----------------------------	----------------------------	-----------------------------

LOCATION OF RELEASE

Opened as Cotton Draw Unit 90

Unit Letter D	Section 36	Township 24S	Range 31E	Feet from the 660	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.179384

Longitude: -103.737840

NATURE OF RELEASE

Type of Release Spill	Volume of Release 700bbls	Volume Recovered 698bbls
Source of Release Produced Water Tank	Date and Hour of Occurrence May 1, 2016 @ 10:00 AM	Date and Hour of Discovery May 1, 2016 @ 10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, OCD	
By Whom? Ray Carter, Asst. Production Foreman	Date and Hour Shelly Tucker, BLM May 1, 2016 @ 5:30 PM Mike Bratcher, OCD May 1, 2016 @ 5:40 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*


A loose wire slipped out of the connection in the battery panel causing the entire battery to lose power and communication shutting down the transfer pumps. The wells to the battery were immediately shut off and a SCADA tech was contacted to fix the issue and get the pumps back going. The battery has been repaired and is back in operation.

Describe Area Affected and Cleanup Action Taken.*

700bbls produced water was released into lined containment. 2bbls of that total amount was carried by the wind out of containment onto location in front of the containment traveling in a Northward direction on location in approximately a 2' x 15' area. All fluid remained on location and a vacuum truck was called and recovered 698bbls produced water from lined containment. Liner was checked for holes and none were found. An environmental agency will be contacted for remediation of the affected area.

Hungry Horse, LLC conducted the remediation for this release in accordance with the BLM and NMOCD approved work plan. The impacted areas outside of lined containment were excavated to depths of 2' BGS. The impacted soil was transported to a division approved facility for disposal. Fresh caliche was used to backfill and the pad was brought back to grade.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION		
Printed Name: Sarah Gallegos-Troublefield	Approved by Environmental Specialist: 		
Title: Field Admin Support	Approval Date: 3/3/17	Expiration Date: N/A	
E-mail Address: Sarah.Gallegos-Troublefield@dmv.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: 3/03/17	Phone: 575.748.1864	FINAL	

2RP-3678