

From: [Bratcher, Mike, EMNRD](#)
To: "Heather Patterson"; hprice@blm.gov
Cc: [Austin Weyant](#); carie@stokeroilfield.com
Subject: RE: Remnant Chama 3 Fed #1
Date: Friday, March 31, 2017 9:28:00 AM
Attachments: [image002.png](#)
[image008.png](#)

RE: Remnant Oil * Chama 3 Fed 1H * 2RP-4088

Heather,

Thank you for the information. As discussed, OCD approves commencement of backfill activities at this site.

Thanks,

Mike Bratcher
NMOCD District 2
811 S. First St.
Artesia NM 88210
575-748-1283 Ext 108
mike.bratcher@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

<end>

From: Heather Patterson [<mailto:heather.patterson@soudermiller.com>]
Sent: Friday, March 31, 2017 8:45 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; hprice@blm.gov
Cc: Austin Weyant <austin.weyant@soudermiller.com>; carie@stokeroilfield.com
Subject: Remnant Chama 3 Fed #1

Mike,

As per our conversation yesterday, SMA will continue with backfill activities today at the Chama 3 Fed #1 (2RP-4088). Attached you will find the site map and tables detailing our delineation of the site. The pad (including the battery) was excavated to 2', while the area over the pipeline in the ditch was excavated to 1.5'. All sidewall and bottom hole samples meet regulatory standards with the exception of L1 bottom hole at 1.5'. Due to safety concerns with the pipeline, this soil could not be removed. We were able to achieve a 10' delineation at L3 to satisfy the C141 conditions of approval.

Thank you for taking the time to meet with me,

Heather Patterson
Staff Scientist

Corporate Registrations: AZ Engineering/Geology/Surveying Firm (14070), SD Surveying Firm (C-7436), TX Engineering Firm (8877), TX Geology Firm (50254), TX PST CAPM (CS-0000051), TX Surveying Firm (10162200), WY Engineering/Surveying Firm (S-1704)



Souder, Miller & Associates

Engineering ♦ Environmental ♦ Surveying

201 Halagueno St

Carlsbad, NM 88220

www.soudermiller.com

(575)200-5343 (mobile)



Notice of Confidentiality and Privileged Status: *This electronic mail message, including all attachments, is for the sole use of the intended recipient(s) and may contain confidential and/or privileged information or otherwise may be protected from disclosure. Any unauthorized review, use, disclosure, distribution or actions which rely on the contents of this information is prohibited. If you are not the intended recipient, please contact the sender and delete the message and any attachment(s) from your system.*

Statement on Viruses and Harmful Software: *While the message and attachment(s) have been scanned with anti-virus software, SMA does not guarantee that this message or any attachment(s) is free of computer viruses or other harmful software. SMA does not accept liability for any damages caused by any computer virus or other harmful software transmitted herewith.*