

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources

Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
 accordance with 19.15.29 NMAC.

fAB1634136488

Release Notification and Corrective Action

nAB1634136647

OPERATOR

Initial Report Final Report

Name of Company HOLLY ENERGY PARTNERS	Contact MELANIE ISENBERG
Address 1602 W MAIN ST	Telephone No. 214-605-8303
Facility Name BARNSDALL LINE	Facility Type CRUDE OIL PIPELINE

Surface Owner BLM	Mineral Owner	API No.
----------------------	---------------	---------

LOCATION OF RELEASE

Unit Letter	Section 26	Township 17S	Range 29	Feet from the	North/South Line	Feet from the	East/West Line	County EDDY
-------------	---------------	-----------------	-------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.8042 Longitude -104.515

NATURE OF RELEASE


Type of Release Crude Oil	Volume of Release 26 Barrels	Volume Recovered 0
Source of Release UNDERGROUND PIPELINE	Date and Hour of Occurrence UNKNOWN	Date and Hour of Discovery 11/17/2016 1420
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD AND NMED	
By Whom? MELANIE ISENBERG	Date and Hour 5/4/2016 NOTIFICATIONS COMPLETED TO BOTH AGENCIES BY 1520	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
 N/A

Describe Cause of Problem and Remedial Action Taken.* A PIPELINE LEAK COMING FROM THE LINE RUNNING FROM THE RJU SOUTH TANK BATTERY INTO THE BARNSDALL LINE. LINE WAS SHUT DOWN AND CREWS WERE DISPATCHED. LEAK WAS FOUND AND REPAIRS ON LINE WERE COMPLETED BY 11/18/16. ALL SOILS REMOVED TO ACCESS PIPELINE WERE REMOVED AND PLACED ON PLASTIC.

Describe Area Affected and Cleanup Action Taken.* PLEASE SEE ATTACHED CLOSURE REPORT.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: MELANIE ISENBERG	Approved by Environmental Specialist: 	
Title: ENVIRONMENTAL ASSOCIATE	Approval Date: 4/3/17	Expiration Date: N/A
E-mail Address: MELANIE.ISENBERG@HOLLYENERGY.COM	Conditions of Approval: Like Approval from BLM	Attached <input type="checkbox"/>
Date: 3/31/2017 Phone: 214-605-8303		

* Attach Additional Sheets If Necessary

2RP-4020