

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Tuesday, April 25, 2017 7:01 AM
To: 'STan Mickle'
Cc: Casey_Summers@oxy.com
Subject: RE: CEDAR CANYON 23 #002H 2RP---3865

RE: OXY * 2RP-3865

Stan,

You might go ahead and send the MSDS sheet for record, but I don't see any issues with it at this point. Water looks good.

Thanks,

Mike Bratcher
NMOCD District 2
811 South First Street
Artesia NM 88210
575-748-1283 Ext 108
mike.bratcher@state.nm.us

From: STan Mickle [mailto:stan.mickle@rxsoil.solutions]
Sent: Thursday, April 20, 2017 7:35 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Cc: Casey_Summers@oxy.com
Subject: CEDAR CANYON 23 #002H 2RP---3865

Hi Mike,

Just wanted to get clearance on using this product to secure my drain system together before active remediation. Next week we begin our process. I will notify you prior to remediating and prior to closure samples for oversight. Also see water quality being used for this project.

Stan Mickle I VP of Operations I RXSoil, Inc.
201 Main Street, Suite 1360, Fort Worth, Texas 76102
Office: 817-996-4653 I Cell: 210-997-7645
stan.mickle@rxsoil.solutions