

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
 accordance with 19.15.29 NMAC.

2RP-2139

fjMW1334640231

Release Notification and Corrective Action

njMW1400356842

OPERATOR

Initial Report Final Report

| | | | |
|-----------------|--------------------------------|----------------|------------------------|
| Name of Company | Enterprise Field Services, LLC | Contact | Alena Miro |
| | PO Box 4324, Houston, TX 77252 | Telephone No. | 575-628-6802 |
| Facility Name | Pipeline ROW, Line A6 | Facility Type: | Gas-gathering Pipeline |
| Surface Owner | BLM | Mineral Owner | NA |
| | | Lease No. | NA |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| | 2 | 25S | 26E | | | | | Eddy |

Latitude: N 32.16419 Longitude: W -104.27445

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|----------------------------|----------------------------|----------------------|
| Type of Release | Natural Gas | Volume of Release | 425 MCF | Volume Recovered: | NatGas - 0 |
| Source of Release | Suspected corrosion leak. | Date and Hour of Occurrence | 12/20/2013 15:00-17:00 MST | Date and Hour of Discovery | 12/20/2013 15:00 MST |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | | | |
| By Whom? | | Date and Hour | | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Suspected corrosion leak. All gas was lost to atmosphere. BLM has been notified.

Describe Area Affected and Cleanup Action Taken.*

To be determined.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--------------------------------------|---|----------------------------------|---|
| Signature: |  | OIL CONSERVATION DIVISION | |
| Printed Name: Jon E. Fields | | Approved by District Supervisor: |  |
| Title: Director, Field Environmental | | Approval Date: 4/26/17 | Expiration Date: N/A |
| E-mail Address: jefields@eprod.com | | Conditions of Approval: N/A | Attached <input type="checkbox"/> |
| Date: 12/20/2013 | Phone: 713-381-6684 | | |

* Attach Additional Sheets If Necessary

2RP-2139