

Received 12/20/2016

NMOCD Dist 2

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**2RP-3298**

fAB1526739986

**Release Notification and Corrective Action**

nAB1526739484



**OPERATOR**☐ Initial Report ☒ Final Report

Name of Company <b>Enterprise Field Services, LLC</b>	Contact <b>Alena Miro</b>
Address <b>PO Box 4324, Houston TX 77252</b>	Telephone No. <b>575-628-6802</b>
Facility Name <b>Pipeline ROW, Marquardt Line</b>	Facility Type <b>Gas Gathering Pipeline</b>
Surface Owner <b>Multiple Produces, SOL</b>	Mineral Owner <b>NA</b>
Lease No. <b>NA</b>	

**LOCATION OF RELEASE**

Unit Letter	Section <b>11</b>	Township <b>25S</b>	Range <b>26E</b>	Feet from the	North/South Line	Feet from the	East/West Line	County
-------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	--------

Latitude **N 32.146674** Longitude **W -104.261086****NATURE OF RELEASE**

Type of Release <b>Natural Gas</b>	Volume of Release <b>76 MCF</b>	Volume Recovered <b>NA</b>
Source of Release <b>Line blow-down for maintenance</b>	Date and Hour of Occurrence <b>3/10/2014 @ 11:00 MDT</b>	Date and Hour of Discovery <b>3/10/2014 @ 12:45 MDT</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* <b>Blow-down to re-route and avoid protected habitat.</b>		
Describe Area Affected and Cleanup Action Taken.* <b>Line and ROW that passes through protected habitat.</b>		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Jon E. Fields</b>	Approved by Environmental Specialist: 	
Title: <b>Director, Field Environmental</b>	Approval Date: <b>4/26/17</b>	Expiration Date: <b>N/A</b>
E-mail Address: <b>jefields@eprod.com</b>	Conditions of Approval: <b>N/A</b>	Attached <input type="checkbox"/>
Date: <b>12/20/2016</b> Phone: <b>713-381-6684</b>		

\* Attach Additional Sheets If Necessary

**2RP-3298**