

**From:** [Weaver, Crystal, EMNRD](#)  
**To:** ["Chuck Johnston"; Bratcher, Mike, EMNRD](#)  
**Subject:** RE: Horse Creek Com #002 C-141  
**Date:** Tuesday, January 17, 2017 4:06:00 PM  
**Attachments:** [image001.png](#)  
[1. 4071 - COAs & signed C-141 intial.pdf](#)

---

RE: Vanguard Operating, LLC. \* Horse Creek Com #2 \* 30-005-61335 \* 2RP-4071

Chuck,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4071.

Thank you,

## Crystal Weaver

Environmental Specialist  
OCD – Artesia District II  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Office: 575-748-1283 ext. 101  
Cell: 575-840-5963  
Fax: 575-748-9720

---

**From:** Chuck Johnston [mailto:[cjohnston@vnrlc.com](mailto:cjohnston@vnrlc.com)]  
**Sent:** Tuesday, January 10, 2017 12:32 PM  
**To:** Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>; Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>  
**Subject:** Horse Creek Com #002 C-141

Crystal, please find the C-141 for the Horse Creek Com #002. Our foreman said it appears to about a 15 ft. X 15 ft. area at the wellhead that is stained from produced water. He said the leak appears to be on the surface casing valve but there is no pressure or water when the valve is open. The crew is make repairs to the well and a backhoe and soil testers will check for depth of contamination before remediating the soil.

Let me know if you have any questions.

**Chuck Johnston**  
**EHS / Operations Specialist**  
**432-202-4771 Cell**

**432-248-8154 Office**

