

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Assault SWD (in TX)	Facility Type	Salt water disposal
Surface Owner	Mineral Owner	API - TX drilling permit #810591	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	14	1	Blk 59					Culberson

Latitude 31.954796 Longitude -104.149549

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	18000 bbls	Volume Recovered	0 bbls
Source of Release	poly pipe gathering line	Date and Hour of Occurrence	8/1/2017 4:00am	Date and Hour of Discovery	8/1/2017 11:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NRC, TXRRRC, OCD		
By Whom?	Stuart Wittenbach	Date and Hour	8/1/2017 1:20 pm		
Was a Watercourse Reached?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	18,000 bbls		

If a Watercourse was Impacted, Describe Fully.*
The produced water entered the Delaware River at the GPS coordinates listed above.

Describe Cause of Problem and Remedial Action Taken.*
The poly gathering line ruptured at the Lateral due to pressure. Absorbant boom was immediately deployed and placed downstream of the impact.

Describe Area Affected and Cleanup Action Taken.*
Water sample points have been set along the Delaware and down into the Pecos, and are sampled daily.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Christine Alderman</u>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Christine Alderman	Approved by Environmental Specialist:	
Title: ESH Supervisor	Approval Date:	Expiration Date:
E-mail Address: calderman@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/3/2017 Phone: 432-853-7059		

* Attach Additional Sheets If Necessary