

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nAB1701355694

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company COG Operating LLC	Contact Robert McNeil
Address 600 West Illinois Ave., Midland, TX 79701	Telephone No. (432) 683-7443
Facility Name Cottonmouth 23 Federal Com 2H Battery	Facility Type Tank Battery

Surface Owner: Federal	Mineral Owner	API No. 30-015-43015
------------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 22	Township 26S	Range 28E	Feet from the 190	North/South Line North	Feet from the 330	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.034786174° Longitude W 104.06753455 °

NATURE OF RELEASE

Type of Release: Oil & Produced Water (fire)	Volume of Release 1 bbl Oil & 9 bbls PW	Volume Recovered 0.5 bbls Oil & 7 bbls PW
Source of Release: Flare	Date and Hour of Occurrence 1/11/17 8:00 pm	Date and Hour of Discovery 1/11/17 8:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher – NMOCD / Shelly Tucker - BLM	
By Whom? Rebecca Haskell	Date and Hour 1/12/17 1:21 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		



Describe Cause of Problem and Remedial Action Taken.*

The release was caused by fluid going through the flare causing a fire. The fire quickly extinguished itself due to the limited amount of fluid that escaped the flare. A vacuum truck was used to remove all freestanding fluids.

Describe Area Affected and Cleanup Action Taken.*

COG inspected site and collected samples to define spills extent. None of the samples collected showed impact above the RRAL's. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
	Approved by District Supervisor: 	
Printed Name: Ike Tavarez (Agent for COG)	Approval Date: 9/27/17	Expiration Date: N/A
Title: Project Manager	Conditions of Approval: BLM Approval	
E-mail Address: Ike.Tavarez@TetraTech.com	Attached <input type="checkbox"/>	
Date: 07/06/17 Phone: (432) 682-4559	FINAL	

* Attach Additional Sheets If Necessary

2RP-4077