

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1702743179

OPERATOR

 Initial Report Final Report

Name of Company	OXY USA INC	Contact	WADE DITTRICH
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-3902828
Facility Name	GETTY 24 FEDERAL #11 CTB	Facility Type	BATTERY
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-31162

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	24	22S	31E	2310	SOUTH	990	EAST	EDDY, NM

Latitude_ N 32.37579° _ Longitude_ W 103.72620° _ NAD83

NATURE OF RELEASE

Type of Release	PRODUCED WATER	Volume of Release	9 bbls	Volume Recovered	33 bbls, Including addition tank water from picking the tank
Source of Release	TANK SPILL	Date and Hour of Occurrence	1-8-2017	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Crystal Weaver-NMOCD, Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	01/10/2017 @ 4:47pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A tank spill caused 9 bbls of produced water to leak out. A vacuum truck recovered 33 bbls of water including additional water from picking the tank.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 20' x 9' on location inside the berm. Remediation was completed in accordance with the remediation plan approved for the release (2RP-4093) by Mike Bratcher of the NMOCD on 4-03-2017 and by Shelly Tucker of BLM on 04/18/2017.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	WADE DITTRICH	Approved by Environmental Specialist:	
Title:	ENVIRONMENTAL COORDINATOR	Approval Date:	10/16/17
E-mail Address:	wade_dittrich@oxy.com	Expiration Date:	N/A
Date:	Phone: 575-390-2828	Conditions of Approval:	Like approval BLM
		Attached	<input type="checkbox"/>
		FINAL	

* Attach Additional Sheets If Necessary

2RP-4093