

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: Bridger, LLC.	Contact: Mel Franklin
Address: 2009 Chenault Drive Ste. 100, Carrollton, TX	Telephone No.: 575-291-9018
Facility Name: Sunoco Pecos River Station Truck Unload	Facility Type: Tank Battery
Surface Owner: Private	Mineral Owner: N/A
API #/Facility #: 5593400000	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	12	28S	23E					

Latitude 32.315733 Longitude -104.050077 NAD83

**NATURE OF RELEASE**

Type of Release: Crude Oil	Volume of Release: 5 bbls	Volume Recovered: -0- bbls
Source of Release: Tank Overflow	Date and Hour of Occurrence: 9/16/2017 @ 10:15 am	Date and Hour of Discovery: 9/16/2017 @ 10:15am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NMOCD - Mike Bratcher, left voicemail	
By Whom? David Adkins	Date and Hour: 9/18/2017 @ 08:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*  Human error resulted in a tank overflow at the Sunoco Pecos River Station. Approximately 5 barrels of crude oil were released into the unlined earthen berms. No fluids were recovered. All fluids remained on location.		
Describe Area Affected and Cleanup Action Taken.* All fluid was contained within the earthen berms. Talon/LPE has been contracted to perform remediation activities.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 

Printed Name: Mel Franklin

Title: Area Operations Manager

E-mail Address: mfranklin@bridgergroup.com

Date: 9/20/2017 Phone: 575-291-9018

**OIL CONSERVATION DIVISION**

Approved by Environmental Specialist:

Approval Date:

Expiration Date:

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary