

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1718739385

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443
Facility Name: Switchback State #021H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner: State	API No.: 30-015-43967
----------------------	----------------------	-----------------------

LOCATION OF RELEASE

Unit Letter P	Section 11	Township 24S	Range 27E	Feet from the 380	North/South Line South	Feet from the 312	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: 32.2253012 Longitude: -104.1704936 NAD83

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 2bbl oil & 40bbl PW	Volume Recovered: 1bbl Oil & 37bbl PW
Source of Release: Water Tank	Date and Hour of Occurrence: 6/30/2017 7:15am	Date and Hour of Discovery: 6/30/2017 7:15am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver-NMOCD Amber Groves-SLO	
By Whom? Rebecca Haskell	Date and Hour: 6/30/2017 11:28pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was due to a split across the bottom of the tank. The tank was replaced.

Describe Area Affected and Cleanup Action Taken.*

The release was contained within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment was pressure washed to remove any residue from the release. The lined containment was inspected and found to be structurally sound.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheldon L. Hitchcock</i>		OIL CONSERVATION DIVISION	
Printed Name: Sheldon L. Hitchcock		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: HSE Coordinator		Approval Date: 10/24/17	Expiration Date: N/A
E-mail Address: slhitchcock@concho.com		Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 10/13/2017 Phone: 575-746-2010		FINAL	

* Attach Additional Sheets If Necessary

2RP-4283