

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Fasken Oil and Ranch	Contact: Aaron Pachlhofer, P.G.
Address: 6101 Holiday Hill RD, Midland, TX 79707	Telephone No.: 432-687-1777
Facility Name: Gossett "20" No. 3H Battery	Facility Type Tank Battery

Surface Owner: Ronald D. Houghtaling	Mineral Owner: State
--------------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter I	Section 20	Township 20-S	Range 25-E	Feet from the 2250	North/South Line South	Feet from the 150	East/West Line East	County Eddy
-------------------------	----------------------	-------------------------	----------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	-----------------------

Latitude 32.558197° Longitude -104.499148°

NATURE OF RELEASE

Type of Release: Oil, Produced water	Volume of Release: 3 oil, unk water	Volume Recovered: 3 oil, 20 water
Source of Release: Sight glasses on vessels	Date and Hour of Occurrence 4/12/17 23:00	Date and Hour of Discovery 4/13/17 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Artesia Mike Bratcher	
By Whom? Vince Hancock	Date and Hour: 4/13/17 14:05 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


Sight glasses on vessels broken due to large hail during storm. Release stopped on discovery. Fluids removed. 3 barrels of oil were released, but an unknown amount of water was released, 2 inches of rain were recorded during the storm that caused the spill. 20 barrels of water were recovered from the containment.

Describe Area Affected and Cleanup Action Taken.*

Affected area confined primarily to inside of battery firewall. Small area of overspray on top of battery firewall and into pasture. Clean up planned for 4/21/17.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist:		
Printed Name: Aaron Pachlhofer, P.G.			
Title: Environmental Coordinator	Approval Date:	Expiration Date:	
E-mail Address: aaronp@forl.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 3/28/17 Phone: 432-687-1777			

* Attach Additional Sheets If Necessary