

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Wednesday, October 18, 2017 1:13 PM
To: Aaron Pachlhofer
Subject: RE: Fasken El Paso Federal No. 12 and Gossett 20 spills

Aaron,

For the Gossett site, the closure report lists "Sample results after the initial removal were:" and then it shows S-1 Surface, S-1 1", S-2 Surface S-2 1".

I have some questions:

- Was the next sample under Surface taken at one inch or one foot? The report suggests one foot, but the data and chain of custody sheet show one inch.
- S-2 Surface returned a value of 9680 mg/kg. Was that removed?
- I believe you did a bio-remediation on everything excavated, including gravel. Is there any analytical data on that material?

Thanks,

Mike Bratcher
NMOCD District 2
811 South First Street
Artesia, NM 88210
575-748-1283 Ext 108

From: Aaron Pachlhofer [mailto:aaronp@forl.com]
Sent: Monday, October 2, 2017 10:26 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Subject: Fasken El Paso Federal No. 12 and Gossett 20 spills

Mike,

Doc Oberding and I had discussed the soil stockpiles remaining at both of these tank batteries, since the concentrations in the excavations were below limits. Two samples from each stockpile were collected. The lab reports for each are attached. I have also attached the original closure requests that I sent to Crystal.

I would like to return the pea gravel to the inside of the firewall at the Gossett.

I would like to allow our operations personnel to re-use the stockpile at the El Paso Federal No .12 at their discretion.

Please call or email with any questions,



Aaron Pachlhofer, P.G.
Environmental Coordinator
Fasken Oil and Ranch, Ltd.

6101 Holiday Hill Road
Midland, TX 79707
432-687-1777 Office
830-377-9190 Cell